

ISOM measurement chart

User Manual

Intended Purpose

The Baseline[®] ISOM Measurement Chart is a 36" x 30" wall chart that illustrates measurement and recording rules as set forth by the American Academy of Orthopedic Surgeons. Complete guideline for measuring and recording as per International Standards of Measurement. Covers goniometry, X-ray evaluation & anthropometric measurement. Chart arrives rolled as it's shipped securely in a mailing tube. Illustrated with numerous images to help with accuracy. Includes charts and recording tables.

How to Install


The Baseline[®] ISOM Measurement Chart can be placed on a wall using your desired hanging method. Simply unroll the chart, and position it on your wall. Secure it with tape, thumb tacks, or another desired hanging method.

WARNING:

- Verify installation height and alignment
- Maintain proper lighting for accurate readings
- Replace if measurement markings become unclear
- Keep away from direct sunlight to prevent fading
- Ensure stable wall mounting
- Verify accuracy of reference points

Disposal Method

Dispose of item in accordance with the local/regional/national/international regulations.



Fabrication Enterprises Inc
250 Clearbrook Road, Suite 240
Elmsford, NY 10523 (USA)
tel: +1-914-345-9300 • 800-431-2830
fax: +1-914-345-9800 • 800-634-5370
FabEnt.com



2862



AJW Technology Consulting GmbH
Breite Strasse 3
40213 Dusseldorf Germany



MedEnvoy
NL-IM-000000248
Prinses Margrietplantsoen 33, Suite 123
2595 AM, The Hague (NL)